


15B/17B/18B Digital Multimeters Quick Reference Guide

⚠ See Users Manual for "Safety Information" and complete operating information.


Fuse Test

0.0 - 0.1Ω = OK


0.099 - 1.01 kΩ = OK




Voltage \tilde{V} \bar{V} \bar{mV}




Resistance Ω




Continuity diagonal line




LED Test (18B Only)




Current \tilde{A} , mA, μA







Capacitance μF




Temperature (17B Only)




Diode Test →





Duty Cycle % (17B Only)



Frequency (Hz) (17B Only)




Relative Δ (Zero) (17B Only)



EXIT
REL

HOLD



ToolPak/MH10 (Optional)

